



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
SANDFORD GROVE ROAD	o/s 82 (opp 75)	Damaging	Extensive kerb disruption - impossible to adequately repair without tree removal	Platanus x hispanica	Plant in new 800mm pit o/s 82 (same as felled tree)	Corylus colurna
SANDFORD GROVE ROAD	opposite 70	Damaging	Kerbstones absent and f/w obstructed, cannot repair to specification without extensive root damage	Platanus x hispanica	Plant in new 800mm pit opposite 70 (same as felled tree)	Corylus colurna